

June 25, 2018

Mitsui Chemicals, Inc.

As of 15:00

Fire at Osaka Works (4th Report)

On 21st of June, a fire broke at Mitsui Chemicals Osaka Works.

Mitsui Chemicals wishes to express deepest apologies to all of its stakeholders, local residents, related authorities and customers for causing such great inconvenience.

As of 15:00 am today, the following details have been determined with regard to the incident.

1. Location

Utility plant

Mitsui Chemicals, Inc. Osaka Works

1-6 Takasago, Takaishi City, Osaka Prefecture, Japan

2. Sequence of Events

June 21, 2018	16:40	A fire broke from a chimney
	16:42	Reported public fire station
June 22, 2018	8:30	Extinguishment of the fire was confirmed

3. Damages

Injuries: None

Facility Damage: Under investigation at waste gas treatment system & chimneys at utility plant. No further damage besides the utility plant has been identified.

4. Impact to outside Works

Under investigation

5. Cause and Action Taken

Mitsui Chemicals plans to implement appropriate measures in accordance with instructions from the local fire department and guidance from relevant authorities.

6. Impact to product shipment

None at this moment

7. Financial impact

Under investigation. We will immediately report if any major impact is anticipated.

Inquiries

Head Office: Corporate Communications Division +81-(0)3-6253-2100

Osaka Works: General Affairs & Human Resources Section +81-(0)72-268-3502